



45	2	Rennchen	NW 25 ND 10	H. 37.11	4
44	2	Stützen	NW 25	H. 00.29	7
43	1	Flansch	NW 100 ND 10	H. 37.11	4
42	1	Stützen	NW 100	H. 00.29	1
41	2	Schweitzlöten			22
40	4	Fl-Eisen	20x25	St. 00.12	1.2
39	2	Rehrhappen	NW 80	H. 00.29	2
38	2	Sasrohre 3'	lg. 160	H. 00.29	4
37	1	Ring	100x110x10	H. 00.29	21
36	1	Muttern	100x16	H. 00.29	82
35	1	Deckel	70x7	H. 00.29	28
34	2	Vertikale Fl.	NW 25	H. 37.11	5
33	15	Schrauben	M 26 x 80	H. 38.13	725
32	4	Schrauben	M 20 x 65	H. 38.13	36
31	2	R-Schra.	30x30x6	H. 00.12	1
30	2	T-Schra.	30x30x6	H. 00.12	49
29	1	Düse	20x10x10	H. 00.29	139
28	1	Rennchen	100x100	H. 37.11	30
27	2	Rennchen	200x200	H. 37.11	230

26	2	Muttern	51/57	H. 38.13	4
25	1	Muttern	100x13	H. 00.29	29
24	1	Deckel mit Rippen	220/160	H. 00.29	179
23	1	Manifol. Übergang	210x16	H. 00.29	710
22	1	Manifol.	210x16	H. 00.29	710
21	1	Ring	100/100	H. 00.29	70
20	6	Rippen	20x20	H. 00.29	46
19	6	Rippen	20x20	H. 00.29	152
18	2	Handschweißnaht	100x10	H. 37.11	8
17	2	Handschweißnaht	100x10	H. 37.11	69
16	2	Rennchen 20x10	100x10	H. 37.11	116
15	1	Rennchen	100x10	H. 37.11	32
14	1	Rennchen	100x10	H. 37.11	324
13	2	Rehrhappen	100x10	H. 37.11	120
12	2	Rehrhappen	100x10	H. 37.11	162
11	1	Muttern	100x16	H. 00.29	112
10	2	"	100x16	H. 00.29	112
9	2	"	100x16	H. 00.29	5
8	2	"	100x16	H. 00.29	10
7	1	"	100x16	H. 00.29	12
6	1	"	100x16	H. 00.29	158
5	1	"	100x16	H. 00.29	11
4	1	Deckel	100x16	H. 00.29	126
3	1	Deckel	100x16	H. 00.29	259
2	1	Manifol.	100x16	H. 00.29	1123

Ammoniakwerk Marsberg G. m. b. H.

M 034 - 2

Gezeichnet: ...

Geprüft: ...

Freigegeben: ...

Prüfungsausschuss für Maßstäbe