



Figure 20. - Fly ash deposits on platen coils—thermocouple 13 at side—after run 34.