



Stückliste 2. zu führen!  
 1. = rechts!  
 1. = links!

Endblech Par. 9 ohne Rundriss  
 Endblech Par. 10 mit Rundriss

|    |   |            |              |         |  |           |
|----|---|------------|--------------|---------|--|-----------|
| 17 | 2 | Bleche     | 20 x 20 x 1  | 1/17.12 |  |           |
| 16 | 2 | Platten    | 20 x 20 x 20 | 1/17.12 |  |           |
| 15 | 1 | Handbohrer | 20 x 20 x 10 | 1/17.12 |  |           |
| 14 | 1 | Blech      | 17 x 3       | 1/17.12 |  | auspassen |
| 13 | 1 | Bleche     | 17 x 3       | 1/17.12 |  |           |
| 12 | 1 | Bleche     | 17 x 3       | 1/17.12 |  |           |
| 11 | 1 | Blech      | 17 x 3       | 1/17.12 |  |           |
| 10 | 1 | Endblech   | 20 x 20 x 1  |         |  |           |
| 9  | 1 | Endblech   | 20 x 20 x 1  |         |  |           |
| 8  | 5 | Handbohrer | 20 x 20 x 10 | 1/17.12 |  |           |
| 7  | 2 |            | 20 x 20 x 10 |         |  |           |
| 6  | 2 |            | 20 x 20 x 10 |         |  |           |
| 5  | 5 | Handbohrer | 20 x 20 x 10 | 1/17.12 |  |           |
| 4  | 1 | Handbohrer | 20 x 20 x 10 | 1/17.12 |  |           |
| 3  | 1 | Handbohrer | 20 x 20 x 10 | 1/17.12 |  |           |
| 2  | 1 | Blech      | 17 x 3       | 1/17.12 |  | auspassen |
| 1  | 1 | Blech      | 17 x 3       | 1/17.12 |  |           |
| 18 | 1 | Handbohrer | 20 x 20 x 10 | 1/17.12 |  |           |

**M 026 - 2**

Technische Abteilung  
 Maschinenbau